## DOUGLA AIRCRAFT COMPANY

3855 Lakewood Boulevard Long Beach, California 90846

May 10, 1977

C1-726-139

DPM 850-8 /monomer, Styrene

Monsanto Company 6670 East Flotilla Street Los Angeles, California 90040

Gentlemen:

This facility must, on occasion, reship your following products:

Styrene Monomer — DPM 850-8

Resin Filler, Santocel 54 — DPM 5480 Answered - See File

Polyimide Resin, Skybond 703 — DPM 5956 Answered See File

In order to insure our compliance with the Hazardous Materials Requilations of the Department of Transportation, Title 49, Code of Federal Regulations, it is requested this office be advised as to whether or not your products are regulated or restricted articles for shipment by surface or air modes of transport.

Should the products be regulated, please indicate:

- 1. DOT Proper Shipping Name per Section 172.101, 49 CFR.
- 2. DOT Hazard Classification per Section 172.101, 49 CFR.
- 3. Flash Point and Closed Cup method per Section 173.115, 49 CFR.
- 4. IATA Article Number.

It is further requested this office be furnished a current copy of the Occupational Safety and Health Administration (OSHA) Material Safety Data Sheet, if available, for all components listed.

Your cooperation and prompt reply will be appreciated.

Very truly yours,

V. Veneroso, Dept. C1-726 (52-11)

Materials Handling & Packaging Engineering

Douglas Aircraft Company

WTJ:rc

MCDONNELL DOUGLAS